

## T8FB Parameter Setup Software Driver Installation for WIN10

### I. First Use

1. Connect T8FB to the computer with a USB cable of data transmission (instead of charging function only) and switch it on




2. Download the driver **PL2303 drive for WIN10 (COM &LPT)** from [www.radiolink.com](http://www.radiolink.com)



> 软件 (D:) > ChromeCoreDownloads > UpgradeDrive > UpgradeDrive


CH340\_Drive(USB Drive) for XP&WIN7  
**PL2303 drive for WIN10 (COM &LPT)**

3. Right click **THIS PC - Manage - Device Manager - Ports - Update Driver Software**




4. Follow the steps to browse to select the downloaded driver and install






II. If there's an exclamation mark appearing when connection, try to install the driver again by following as below



1. Right click **THIS PC - Manage - Device Manager - Ports - Update Driver Software**



## 2. Browse my computer for driver software



## 3. Pick from a list of device drivers on my computer



4. Pop out as below will display when the driver is updated successfully

